

RECOMMEND THAT THE COMPASS HARNESS BE REPLACED THROUGH WING CONDUIT (FROM L1 RECEPTACLE TO COMPASS XMTR) USING NEW "H" FILM WIRE ON ARTICLE 383 AS WELL AS ALL OTHER PROJECT ARTICLES.

IF DESIRED, WILL SUBMIT A MESSAGE QUOTE TO PROVIDE REQUIRED S/B KITS.

S E C R E T TOR: 891713Z MAY 67

SECRET SCIUNT PROVIDENCE PROVIDEN